| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------------------|---|-----------------------|---|--|---|--|---|--|-------------------------------|
| SITE | UTILITIES | | | | | | | | |
| 39 | Site Water | Accessibi | | Provide Backflow Preventer | Provide Backflow Preventer | MCA limit concerns, no work | Provide Backflow Preventer | TF already has two backflow preventers, one for each side | Provide Backflow Preventer |
| <u>SITE </u> 44 | FEATURES Stormwater Management System | H1- Useful Life | Stormwater management (Staff Parking storm pipe replacement) | | Repair/replace failing stormwater management systems (baseball field pipe failure, add drain at communication box between two fields, north parking inlets at lawn failing) | | | Stormwater management (improve drainage at garage bays, District and Town sides. Replace concrete apron, bollards, tie roof leaders to underground | |
| 55 | Pavement | H1- Useful Life | Repave Staff Parking (full depth) | | | | Replace pavement (full depth, additional signage, new curbing, storm pipe scope) | stormwater system) Replace failed pavers around roof leader near main entrance with concrete pavement, District | |
| 58 | Athletic Fields | H1- Useful Life | Replace Track Replace Turf | | | | | | |
| 60 | Athletic Structures | Improve ments | Three new scoreboards (baseball, softball, soccer/lacrosse) and delay of game clocks for Turf Field | | | | | | |
| ARCH 61, 66 | ITECTURAL Masonry Restoration | | Masonry restoration: Brick repointing, masonry repair Repair chipped, cracking, | Repointing, Repairing Repair Chipped, | balance of masonry Repair Chipped, | repair intended to be Change Order to Project 2021 | Masonry Restoration: Repointing, Repairing | - | |

| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------|------------------------------|-----------------------|--|---|--|---|---|---|---|
| 69 | Exterior Doors | H1- Useful Life | Provide secure card access at two exterior doors (H2) | | Replace existing FRP and aging doors to match new doors | Provide secure card access at exterior door near playground (H2) | | Replace man door at bus wash | |
| 73 | Roof | H1- Useful Life | | | | | Add snow guards to the roof | Replace roof | |
| 65 | Structural Floors | H1- Useful Life | Add fireproofing where missing at existing metal decks (music and tech wings) | | | | | Town side interior bay drain replacement | |
| 77, 78 | Flooring | H1- Useful Life | Minor tile floor repair at boys locker room | | Replace Cafeteria flooring | | | | |
| 80, 92 | Ceilings | H1- Useful Life | In Ceilings, repair HVAC system leaks, slab leaks and replace damaged ceiling tiles, 18 rooms | In Ceilings, repair HVAC system leaks and replace damaged ceiling tiles, 5 rooms | In Ceilings, repair HVAC system leaks, slab leaks and replace damaged ceiling tiles, 2 rooms | In ceilings, repair system leaks and replace damaged ceiling tiles | In ceilings, repair cause of leaks in Corridor 119 | | |
| 81 | Lockers | H1- Useful Life | Corridor improvements, including locker replacement | Corridor improvements, including locker replacement | | | | | |
| 82 | Interior Doors | H1- Useful Life | Door replacement, 68 doors (addressing fire rating, door hardening and accessibility) | | Hardware handset replacement, 55 sets (addressing fire rating, door | | Door hardware replacement (H2) (replace three double door hinges to reduce gap for fire rating) | | |
| | Vertical Transportation | H1- Useful Life | | Replace enclosed Corridor Lift | hardening and | | | Replace Bay 2 vehicle lift | |
| - | Handicapped Accessibility | | Restroom renovations throughout building, (beyond useful life and accessibility concerns) | Gang Restroom renovations including associated custodial rooms | | | | Renovate front desk to be accessible | |
| | Passive Radon Mitigation | | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) | mitigation (suggest testing during | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) | Radon testing and subsequent mitigation (suggest testing during Thanksgiving Break) |

| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------|---------------------|----------|--|-----------------------|----------------------------------|-----------------------|-------------------------|---------------------------------|--------------------------|
| | Access / Wayfinding | | After school single point of HSMS entry | | | | | | |
| | Educational Program | H1- | HS Gymnasium - systems | | SS Gymnasium - | | | | |
| | Spaces (Full | Useful | beyond useful life | | systems are beyond | | | | |
| | Renovation) | Life | (refinish floor, replace | | useful life | | | | |
| | | | partition with curtain, | | (refinish floor, replace | | | | |
| | | | address cracks in CMU, | | partition with curtain, | | | | |
| | | | door repair, replace | | repair/rate door, | | | | |
| | | | bleachers - existing were | | replace basketball | | | | |
| | | | relocated from original | | and volleyball | | | | |
| | | | HS Gym, replace AHU | | systems, replace wall | | | | |
| | | | valve packages, paint) | | pads, replace air | | | | |
| | | | | | handling | | | | |
| | | | | | unit/ductwork/expose | | | | |
| | | | | | ceiling, replace | | | | |
| | | | | | lighting, paint space, | | | | |
| | | | | | improve acoustics, PE | | | | |
| | | | | | office bathroom ADA upgrades) | | | | |
| | | H1- | HS FACS Classroom | | upgraues) | | | | |
| | | | (entire space beyond | | | | | | |
| | | | useful life, undersized) | | | | | | |
| | | | HS Athletic Team Rooms | | | | | | |
| | | Useful | | | | | | | |
| | | Life | | | | | | | |
| | | | Replace HS Greenhouse, | | | | | | |
| | | | including masonry | | | | | | |
| | | Life | (widely used program | | | | | | |
| | | | space causing significant | | | | | | |
| | | | water damage) | | | | | | |
| | | H3- | Classroom | Classroom | | | | | |
| | | Improve | Improvements | Improvements | | | | | |
| | | ments | (Identify specific | (Identify specific | | | | | |
| | | | | improvements during | | | | | |
| | C SYSTEMS | | design) | design) | | | | | |

| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------|--|--|---|--|--|--|---|--|--|
| 89, 92 | Heating | H1- Useful Life | | | Replace unit ventilator at Conf 102; Replace AHU condensing unit at Main Office, Replace 5 heating pumps (Boiler Room and Cafeteria) | | Replace VAV terminals | Replace two rooftop heat exchangers | |
| 90 | Ventilation System (exhaust fans, etc.) | Useful Life H2-HSW Accessibi lity H2-HSW Accessibi lity | (to Basement workshop, Athletic Director H109, Offices H118A, H118B, | Add exhaust and/or ventilation (to Art Room, 5 Science Rooms, BOCES M142, Library Work Room, ISS) | Add exhaust and make-up air systems to Crawlspace adjacent to Elevator Machine Room due to moisture issues Add ventilation (to Kitchen, Office 124A, Exam 127A, 2nd floor Custodial Office) | Replace Reading Suite FCU and Condensing Unit. | | Add Ventilation and Exhaust (to Shop) | Add Ventilation and Exhaust (to Staff area, Vehicle Storage) |
| | Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, | Accessibi lity | Provide refrigerant line covers between Fitness room and Computer Lab H157 | | | | | | |
| | Ducted Heating and Cooling Distribution Systems | H2-HSW Accessibi lity | | | Provide CO and gas detection for Boiler Room, tie into DDC (direct digital controls) systems | | Provide appropriate heat/cooling control | | |

| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------|----------------------|-----------------------------|---|--|---|--|-------------------------|---|--------------------------|
| 94 | HVAC Control Systems | H2-HSW Accessibi lity | | Tie Corridor/ Vestibule heating system into DDC (direct digital | | | | | |
| | IBING | - | | | | | | | |
| 95 | | H1- Useful Life | Replace remaining galvanized piping and Insulate domestic water line in Weight Room vestibule and Stage Prep areas | | Replace remaining galvanized piping | Insulate domestic water piping in two rooms | | Replace Bus Wash System and wall covering | |
| 96 | Sanitary System | H1- Useful Life | Investigate and rectify sanitary systems backing up in Boys Locker Room | | Provide sump pump in Crawlspace and water penetration control | | | | |
| | Drainage System | H1- Useful Life | Investigate and rectify storm piping adjacent to Boiler Room backing up | | | | | | |
| 98 | Hot Water Heaters | H1- Useful Life | | | Replace domestic hot water recirc pump | | | | |
| 99, 100 | Plumbing Fixtures | H2-HSW | Provide eye wash station at Nurse's Suite | | Hand wash sink piping in Kitchen not plumbed correctly, rectify Replace water cooler with bottle filling | Replace mixing valve for Kitchen (H1) Add eye wash station in Nurse's Suite | | | |
| | TRICAL | | | | ···· | | | | |
| | | Accessibi | Add additional electric panels, no further capacity | | | | | | |

| BCS Ref # | Scope Туре | Category | High School (HS) | Middle School (MS) | State Street (SS) | Waterman Elem (WE) | District Office (DO) | Transportation Facility (TF) | Maintenance Barn (MB) |
|--------------|--|-----------------------------|---------------------|--|---|--|--|---|--------------------------|
| | Emergency/ Exit Lighting Systems | Accessibi lity | | lighting, egress/exit lighting as required by | Add emergency lighting, egress/exit lighting as required by new Code | lighting, egress/exit lighting as required by | lighting, egress/exit lighting as required by | Add emergency lighting, egress/exit lighting as required by new Code | |
| 106 | Emergency or standby power system | H2-HSW Accessibi lity | | | | | | Provide Generator | |
| 107 | Fire Alarm Systems (manual, automatic fire detection, and notification appliances) | H1- Useful Life | | | Replace Fire Alarm System, end of useful life | | | | |
| 109 | Communication Systems | H1- Useful Life | | | Replace paging and clock system | Replace paging system | | | |

General Notes:

Scope Categories

H1 - Infrastructure - Useful Life (System at or Near End of Useful Life)

H2 - Infrastructure - Health, Safety, Accessibility (and Code)

H3 - General and Educational Space Improvements

Schedule

| October 6, 2020 | Project 2023/24 Scope Review with BOE |
|---------------------|---------------------------------------|
| October 20, 2020 | BOE Resolution / SEQRA |
| December 8, 2020 | Referendum Vote |
| Jan 2021 - Dec 2021 | Design |
| Dec 2021 - Aug 2022 | SED Review |

| BCS Scope | Type Categ | ory High School | Middle School | State Street | Waterman Elem | District Office | Transportation | Maintenance Barn |
|------------------|------------|--|---|--------------|---------------|-----------------|----------------|------------------|
| Ref # | | (HS) | (MS) | (SS) | (WE) | (DO) | Facility (TF) | (MB) |
| - | | Nov 2022 - Mar 2022 May 2023 - Nov 2024 | Bidding and Award Construction and Close | e-Out | | | | |